

912D PGM 3-Way Garment Rolling Rack

Assembling Guide

- (1) **BASE** 1 pc.
- (2) **SPRING** 1 pc.
- (3) **INNER POLE** 1 pc.
- (4) **OUTER POLE** 1 pc.
- (5) **3 WAY ARM** 1 pc.
- (6) **TOPPER** 1 pc.



(1)



(2)



(3) (4)



(5)



(6)




Step 2

Gently place SPRING on top of the BASE.

Step 1
Place BASE firmly on the ground.

Step 3
Insert INNER POLE into the BASE through SPRING.




Make sure to twist the screw tightly after INNER POLE is inserted into the BASE completely.



Step 4

Slide OUTER POLE over INNER POLE.



The top of INNER POLE must be aligned like this when stepping down the foot pedal.



When you are sliding OUTER POLE over INNER POLE, make sure you are stepping down on the foot pedal with the top of INNER POLE aligned

Step 5
Install 3 WAY ARM.



Twist the screw tightly.



Step 6
Install TOPPER

Congratulations !!!!! Installation complete.